NASA TECH BRIEF



NASA Tech Briefs are issued to summarize specific innovations derived from the U.S. space program, to encourage their commercial application. Copies are available to the public at 15 cents each from the Clearinghouse for Federal Scientific and Technical Information, Springfield, Virginia 22151.

Conversion of Continuous-Direct-Current TIG Welder to Pulse-Arc Operation




Fig. 1. Pulse Circuit

Fig. 2. High-Low Current Control

The problem:

To convert a continuous-dc TIG (tungsten-inert gas) welder for pulse-arc operation.

The solution:

Addition of an electronics package without which the machine can continue to function in its original mode. The package allows presetting of the pulse rate, duty cycle, and current value, and enables welding of various alloys and thicknesses of materials. (See figs. 1-3.)

Pulse-arc welding gives better control of penetration by the weld, minimizes the shrinkage effect of great heat, and helps to reduce porosity of the weld.

Notes:

- 1. Normally, pulsed-arc equipment must be purchased as a separate unit, and an existing continuous unit cannot be modified for pulsed modes. Pulsed-arc TIG welding provides advantages over conventional TIG welding for out-of-position welds and for thin metals. This information may be of general interest to all welding fabricators.
- No further documentation is available. Inquiries may be directed to:

Technology Utilization Officer Marshall Space Flight Center Huntsville, Alabama 35812 Reference: B69-10393

(continued overleaf) .

This document was prepared under the sponsorship of the National Aeronautics and Space Administration. Neither the United States Government nor any person acting on behalf of the United States

Government assumes any liability resulting from the use of the information contained in this document, or warrants that such use will be free from privately owned rights.

Patent Status:

No patent action is contemplated by NASA.

Pulse Rate

Source: D. R. Lien of North American Rockwell Corporation under contract to Marshall Space Flight Center (MFS-16411)

For Setting Low
P.B.

Current Selection

B

Duty Cycle

Fig. 3. Examples of Pulse forms at Different Current Values (A), and the Control Panel of the Package (B)

Current